

Change History file..

=====

2012-06-11

Change History for IBM Switched and monitored Power Distribution  
Units (46M4002, 46M4003, 46M4004, 46M4005)

# **Change History for IBM Switched and Monitored pdu\_v01.2\_1**

June 11, 2012

# **Table of Contents**

0.0 Introduction.....	3
1.0 Enhancements .....	3
1.1 Initial release OPDP_sIBM_v00.1_0302.....	3
2.0 Problems Fixed .....	3
2.1 Initial release OPDP_sIBM_v00.1_0302.....	3
2.2 Firmware release OPDP_sIBM_v00.1_0607.....	3
2.2.1 Release Summary .....	3
2.2.2 Detailed descriptions and solutions.....	4
2.3 Firmware release OPDP_sIBM_v00.1_0624.....	5
2.3.1 Release Summary .....	5
2.3.2 Detailed descriptions and solutions.....	5
2.4 Firmware release OPDP_sIBM_v01.0_0.bin.....	7
2.4.1 Release Summary .....	7
2.4.2 Detailed descriptions and solutions.....	7
2.5 Firmware release OPDP_sIBM_v01.1_1.bin.....	8
2.5.1 Release Summary .....	8
2.5.2 Detailed descriptions and solutions.....	8
2.6 Firmware release OPDP_sIBM_v01.2_0.bin.....	9
2.6.1 Release Summary .....	9
2.6.2 Detailed descriptions and solutions.....	10
2.7 Firmware release OPDP_sIBM_v01.2_1.bin.....	11
2.7.1 Release Summary .....	11
2.7.2 Detailed descriptions and solutions.....	12

## 0.0 Introduction

This document is to log the change history of the Potencia PDU firmware. We categorized the firmware change into two parts:

- 1) Firmware function enhancement,
- 2) Problems fixed

For Potencia PDU firmware, each release is coded by date. For example, the Potencia PDU initial firmware (MP) is OPDP\_sIBM\_v00.1\_0302, which means it was release on 03-02-2010.

## 1.0 Enhancements

This section describes the new required/added PDU functions to enhance PDU functionality.

### 1.1 Initial release [OPDP\\_sIBM\\_v00.1\\_0302](#)

The firmware version [OPDP\\_sIBM\\_v00.1\\_0302](#) is the official release and approved by IBM to be MP version.

## 2.0 Problems Fixed

This section describes the release history to fix any defect issues of Potencia PDU.

### 2.1 Initial release [OPDP\\_sIBM\\_v00.1\\_0302](#)

The official release and approved Potencia PDU firmware is [OPDP\\_sIBM\\_v00.1\\_0302](#).

### 2.2 Firmware release [OPDP\\_sIBM\\_v00.1\\_0607](#)

#### 2.2.1 Release Summary

Within this release, we fixed:

- 1) Defect item #503974 – TFTP firmware upgrade fails with Linux environment (atftpd and tftpd).
- 2) Defect item #503975 – DHCP fails if with zeros in IP octet

## 2.2.2 Detailed descriptions and solutions

### 1) Defect item #503974 - TFTP firmware upgrade fails with Linux environment

#### Symptom:

When attempting to update the firmware on the Potencia PDU from the web interface using TFTP, if the IP address of the TFTP server entered ends with 255 in the last octet, the TFTP upload fails.

Note that this is a scenario where 255 is valid in the last octet (the subnet mask was 255.255.192.0 and the server IP was 192.168.0.255).

#### Root Cause Analysis:

According to RFC 2349, timeout value should be within the range of (1 ~ 255). As IBM captured data, the timer timeout value is 60000, which is out of range. The out of range timeout value could potentially cause the TFTP download failure.

#### Solution:

By setting the timer timeout value to be the correct value (to be 100) as described in RFC2349, we verified it, in the same procedure of IBM, to be able to fix this problem.

### 2) Defect item #503975 – DHCP fails if with zeros in IP octet

#### Symptom:

When the Potencia PDU attempts to DHCP, it will fail, if one of at least three conditions occur:

1. The static address was set, with an IP address with a zero in one of the octets, and then the Potencia is set to DHCP. In this case DHCP discover shows up in a network trace as truncated.
2. The static address was set, with an IP address without a zero in one of the octets, and then the Potencia is set to DHCP and the DHCP server hands out an address with a zero in one of the octets. In that case, the DHCP discover from the Potencia is OK, but the DHCP request from the Potencia is truncated.
3. Both the static and offered IP addresses do not have zeros in any of the octets, but the server-identifier in the offer has a zero in one of the octets. In this case, the DHCP request from the Potencia PDU will be truncated.

It appears that the reason for all of these errors probably has the same root cause-- whatever code is putting the IP addresses into the DHCP packets in the Potencia PDU is interpreting the zero in one of the IP address octets as a string terminator and truncating the packet at that point.

#### Debug Action:

If there are no zeros in any of the IP address octets, the DHCP from the Potencia PDU does work.

**Root Cost Analysis:**

As calculated the length of the DHCP option, we used the "strlen" of the standard C library. However, 0x00, which as described in the IP address, is treated as terminated character and cause "strlen" function to return incorrect DHCP option length. This incorrect length causes the incorrect interpretation of the DHCP protocol, and then terminates the DHCP handshaking between DHCP client (Potencia PDU) and DHCP server.

**Solution:**

Instead of using standard C library (strlen), we calculate the real length, for example, 192.168.0.1, we calculate the length to be 4 (bytes). With this solution, we verified it to be able to fix this problem.

## **2.3 Firmware release [OPDP\\_sIBM\\_v00.1\\_0624](#)**

### **2.3.1 Release Summary**

Within this release, we fixed:

- 1) Defect item #22770 – The firmware name is too long and will be truncated as doing firmware upgrade.
- 2) Defect item #22771 – PDU fails download if address ends in .255
- 3) Defect item #22808 – PDU TFTP firmware update fails
- 4) Defect item #22809 – PDU telnet cannot use "." character

### **2.3.2 Detailed descriptions and solutions**

- 1) Defect item #22770 – The firmware name is too long and will be truncated as doing firmware upgrade.

**Symptom:**

The switched and monitored Power Distribution Unit (PDU) firmware update Process through the web browser may fail as the text field truncates the text, removing the last characters from the file name.

**Root Cost Analysis:**

The filename is set to be 32 characters. If it is more than 32 characters, it will be truncated, as described.

**Solution:**

We enlarge the size of the filename to be 64 characters to fix this problem. (Please be noted that the MIB file of AEM define this field to be max. 32 characters.)

- 2) Defect item #22771 – PDU fails download if address ends in .255

**Symptom:**

In cases where a server address ends with a 255 octet, the Switched and monitored Power Distribution Unit (PDU) firmware update process will fail stating that it is unable to download the file.

When attempting to update firmware through the web browser, a Trivial File Transport Protocol (TFTP) server address is requested. The server is reachable from the PDU, however, the download displays an error.

**Root Cost Analysis:**

We verify the field to be valid from 0 ~ 254, and will cause reported problem, as the field is 255.

**Solution:**

We correct the field value from 0 ~ 255 to fix the problem.

- 3) Defect item #22808 – PDU TFTP firmware update fails

**Symptom:**

When updating the Switched and Monitored Power Distribution Unit (PDU) firmware through the web interface with the target file residing on a Linux server, an error may occur stating the following:

TFTP Connection Message  
Connect Failed !  
Please Check TFTP IP Address, File Name or Firewall Setting !

**Root Cost Analysis:**

The TFTP option - tsize and ttimeout cause this problem.

**Solution:**

Remove the limitation of tsize and ttimeout to fix this problem.

- 4) Defect item #22809 – PDU telnet cannot use "." character

**Symptom:**

If attempting to change the Internet Protocol (IP) address of the Switched and Monitored Power Distribution Unit (PDU) via Telnet, the user will not be able to input the dot (.) character.

**Root Cost Analysis:**

This is a bug of ignoring the input of ".".

**Solution:**

We modify the code to take care of the input of "." character to fix it.

## **2.4 Firmware release *OPDP\_sIBM\_v01.0\_0.bin***

### **2.4.1 Release Summary**

Release date: 12/7/2010

Please be noted that we updated the release version to OPDP\_sIBM\_ **v01.0\_0**, instead of v00.1\_0.xxxx (xxxx is the release day).

Here v01.0\_0, **this release code is Delta internal release for QE test**

v01.0\_0, **this release code is the release for customer to indicate a “minor” change**

v**01.0\_0** **this release code is the release for customer to indicate a “major” change**

Within this release, we fixed:

- 1) The DHCP issue, which the assigned IP will be 0.0.0.0, if the original IP have one “0”, e.g. 192.168.0.2.
- 2) We create a new function for end-user to reset ADMIN/USER login IDs and Password.

### **2.4.2 Detailed descriptions and solutions**

- 1) The DHCP issue to handle assigned IP address

**Symptom:**

If there is any “0” for IP, at the time to “ENABLE” DHCP function, the assigned IP address from DHCP server will be 0.0.0.0

**Root Cost Analysis:**

This is a bug. As DHCP assigned a reasonable IP address, the DHCP client (PDU) have a bug to handle this assigned IP address after comparing with the original IP and cause the problem to assign 0.0.0.0 as the IP for PDU.

**Solution:**

We fixed this bug and had verified it.

- 2) the reset ADMIN/USER login ID and password function via reset button

**Symptom:**

As end-user forgot or meshed up the login ID and password, there is no way for end-user to reset the meshed up login ID and/or password. Therefore end-user can not to operate/control this PDU.

**Root Cost Analysis:**

New feature added.

**Solution:**

We added a new feature to allow end-user to reset password via reset button. Remotely reset login-ID and password is not provided, regarding to security issue. Only the maintainer aside the PDU can reset the login-ID and password locally.

Here we re-defined the function of the reset button:

- a) If end-user **“hold” the reset button for 2 seconds and then release the reset button**, the **login-ID and password will be restored to default**, which is ADMIN/1001 for ADMIN level, and USER/1000 for user level, no matter what it is before.
- b) If end-user **“hold” the reset button for 8 seconds**, no matter whether he/she **release the reset button, the system will be restarted (software restart)**
- c) Please be noted that both (a) and (b) reset function (reset login-ID/password and system restart) will not affect any output during proceeding these functions.

## **2.5 Firmware release [OPDP\\_sIBM\\_v01.1\\_1.bin](#)**

### **2.5.1 Release Summary**

Release date: 2/18/2011

Please be noted that we change the release coding to OPDP\_sIBM\_vxx.yy\_zz.bin. Please refer to section 2.4.

Within this release, we fixed:

- 1) The ENP (Environmental Probe)
- 2) The algorithm to enhance the communication between WEB board and Meter board.
- 3) The firmware upgrade mechanism and interface to download the meter firmware via network, i.e. to upgrade the meter firmware remotely. (New added function)

### **2.5.2 Detailed descriptions and solutions**

- 1) The ENP (Environmental Probe) issue

**Symptom:**

Sometimes, the ENP is not detected.

**Root Cost Analysis:**

This is a bug. The ENP loses communication with WEB board.

**Solution:**

We fixed this problem by adding the heart-beat to assure the communication with WEB board.

2) The communication confliction between WEB board and meter board

**Symptom:**

As reported issue, the SNMP access is fail.

**Root Cost Analysis:**

This is caused due to RS-232 communication confliction between WEB board and meter board. Since this failure, the WEB board is not able to build up the outlet table. Therefore the SNMP access will be failure since the outlet table is "empty".

**Solution:**

Instead of asking micro-controller (x2) of meter board to initialize the communication with micro-controller of WEB board, we modify the control scheme, initializing by the micro-controller of WEB board to get rid of communication confliction.

3) The mechanism to update the meter firmware via WEB board through network (remotely).

**Symptom:**

New added function.

**Root Cost Analysis:**

New added function.

**Solution:**

We create an interface on the embedded WEB server so end-user can upgrade meter firmware via this interface.

## **2.6 Firmware release [OPDP\\_sIBM\\_v01.2\\_0.bin](#)**

### **2.6.1 Release Summary**

Release date: 8/18/2011

Within this release, we resolved following reported issues:

1. History log stop logging data
2. The history log has wrong value
3. The history log displays incorrect label for outlet 9~12
4. The HTTP security concern when using curl tool to get XML data
5. The SNMPv3 contents of the msgAuthoritativeEngineBoots and the msgAuthoritativeEngineTime fields are incorrect
6. Change the ex-factory default Relay setting from “Relay-All-OFF” to Relay-All-ON”, required by IBM (Specification change.)

## **2.6.2 Detailed descriptions and solutions**

- 1) History log stop logging data & wrong value ((1) & (2))

**Symptom:**

The power usage, as light load, is not updated.

**Root Cost Analysis:**

This is a bug. As light load, the algorithm may just ignore the energy usages.

**Solution:**

We fixed this problem by adjust the algorithm to response light load case.

- 2) The history log displays incorrect head label for outlet 9~12

**Symptom:**

The head labels of the history are incorrect – the labels for outlet 5 ~ 8 showing twice but no labels for outlet 9 ~ 12.

**Root Cost Analysis:**

There is a bug as printing out the head label.

**Solution:**

Fixing this bug by correcting the label printout.

- 3) The HTTP security concern when using curl tool to get XML data.

**Symptom:**

The problem is that the logon ID and password are shown in the output file when the command below is run. It looks like the output file has far more information than is needed by the command.

**Root Cost Analysis:**

The reason of show up the user account and password in curl command is that the embedded web server didn't process the request XML file with login-check, so it will send out unknown data, including account and password information.

**Solution:**

We fix this issue by filtering out the security concerned parameters.

- 4) The SNMPv3 contents of the msgAuthoritativeEngineBoots and the msgAuthoritativeEngineTime fields are incorrect

**Symptom:**

The problem occurs either while using AEM or while using an external client (I am using Net-SNMP) to issue SNMPv3 requests. I currently have Potencia PDUs at firmware version OPDP\_sIBM\_v00.1\_0223 and configured for SNMP authNoPriv. When I issue the SNMPv3 requests, I notice that the response always has the same value for msgAuthoritativeEngineBoots (1) and msgAuthoritativeEngineTime (0).

**Root Cost Analysis:**

There is a bug to access the values of the msgAuthoritativeEngineBoots and the msgAuthoritativeEngineTime (0).

**Solution:**

We fix this issue by accessing the values correctly.

- 5) Change the ex-factory default setting of the Relays from “Relay-All-OFF” to “Relay-All-On”

**Symptom:**

This is a specification change, required by IBM

**Root Cost Analysis:**

This is a specification change, required by IBM.

**Solution:**

Following IBM’s requirement, we change the default setting from Relay-All-OFF to Relay-All-ON.

## **2.7 Firmware release [OPDP\\_sIBM\\_v01.2\\_1.bin](#)**

### **2.7.1 Release Summary**

Release date: 2/17/2012

Within this release, due to MIB file change required by IBM, we modified the PDU firmware to add following functions accordingly:

1. ibmPduPhaseLastPowerReading
2. ibmPduThermalLastReading
3. ibmPduHumidityLastReading
4. ibmPduOutletLastPowerReading

- 5. ibmPduExtThermalLastReading
- 6. ibmPduExtHumidityLastReading

## 2.7.2 Detailed descriptions and solutions

- 1) ibmPduPhaseLastPowerReading

**Symptom:**

New add function to read phase last power.

**Root Cost Analysis:**

New add function..

**Solution:**

New add function.

- 2) ibmPduThermalLastReading

**Symptom:**

New add function to read last temperature.

**Root Cost Analysis:**

New add function..

**Solution:**

New add function.

- 3) ibmPduHumidityLastReading

**Symptom:**

New add function to read last humidity.

**Root Cost Analysis:**

New add function..

**Solution:**

New add function.

- 4) ibmPduOutletLastPowerReading

**Symptom:**

New add function to read outlet last power.

**Root Cost Analysis:**

New add function..

**Solution:**

New add function.

5) ibmPduExtThermalLastReading

**Symptom:**

New add function to read external last temperature.

**Root Cost Analysis:**

New add function..

**Solution:**

New add function.

6) ibmPduExtHumidityLastReading

**Symptom:**

New add function to read external last humidity.

**Root Cost Analysis:**

New add function..

**Solution:**

New add function.