TS7700 Release Notes - 8.52.101.12 (R5.2 Phase 1 PGA1)

IBM System Storage TS7700

Release Notes for the TS7700 (3957 VED / VEC)

• EC: P25715 released March 25, 2022

New Function Supported:

- Quality Fixes (field and backlog)
- 1160 60F and 60G tape drives
- JE and JM media

TS7700 CODE REQUIREMENTS

TS7700	8.52.101.12 (EC P25715, PN 02XY282, PN 02XY283, PN 02XY284, PN 02XY285 (DVD 1, 2, 3 & 4))
DB2	DB2 v11.5.4.0 Informational tokens are "DB2 v11.5.4.0", "s2006161200", "DYN2006161200AIX",and Fix Pack "0"
AIX Base Level	AIX 7.2.5.0
AIX Fixpack	7200-05-01-2038+06
P9 Server Firmware	FW950.00 (VL950_045)
P8 Server Firmware	FW860.90 (SV860_226)
ТСТ	Version= 1.1.8-1281
Cloud Support	IBM Cloud Object Storage System (COS) appliance solution Version 3.15.7.43 April Maintenance Release (Storage_COSS_3.15.7.43) / S3 Protocol AWS, S3 Protocol
TS4500 (Anaconda) Firmware	1800-C00
TS3500 (Anaconda) Firmware	H015
3592 E06 Tape Drive 3592 E07 Tape Drive 3592 E08 Tape Drive 3592 60F Tape Drive	D3I2_883 D3I3_DCB D3I4_B12 D3I5_78D
TSSC	9.2.16
3956-CSB (2072-312 V5030E) 3956-CFC (2072-3N4	8.4.0.5

V5035E)	
Firmware	
HDD (3956-CSB / 3956- XSB)	Seagate Evans Non-SED 7200 rpm, 3.5 inch, 10TB, SAS 12Gb/s 4Kn / FW BCL4
	Seagate Tatsu Non-SED 7200 rpm, 3.5 inch, 10TB, SAS 12Gb/s 4Kn / FW IvI BCGA
	Seagate Mobula Non-SED 7200 rpm, 3.5 inch, 10TB, SAS 12Gb/s 4Kn / FW IvI BCHB
SSD (3956-CFC / 3956-XFC)	Samsung 1643A SSD tier1_flash, 2.5 inch, 3.84TB, SAS 12Gb/s / FW IvI MS73
3956-CSA Firmware	08.40.60.01
Storage Manager GUI	11.30.0A05.0037 Storage Manager GUI level
GKLM	4.1.0.1
Atape	13.0.45.0
GPFS	GPFS Release 5.1.0.3
ITDT	9.3.0.20181029
AIX Diagnostics CD	Version 7.2
16Gbit Cisco Switch	BIOS level 2.1.17
Firmware	Kickstart software level 6.2(9)
	System software level 6.2(9)
VTD EXECs	

Platform Requirements Matrix

Test	Software Level
zOS	V2R4
zTPF	1.1
zVM	6.3, 6,4

zVSE	5.2, 6.1, 6.2

Switch and Channel Extender Support Matrix

Product Vendor and Model	Product Levels of Microcode Supported
Brocade 8510-8 IBM 2499-816 (SAN768B-2)	8.2.3b
Brocade 8510-4 IBM 2499-416 (SAN384B-2)	8.2.3b
Brocade 6510 IBM 2498-F48 8, 16 GB/sec (SAN48B-5)	8.2.3b
Brocade 7800 IBM 2498-R06 (SAN06B-R)	8.2.2b
Brocade 7840 IBM 2498-R42 (SAN42B-R)	8.2.3b
Brocade X6-8 IBM 8961-F08 (SAN512B-6)	9.0.1c,8.2.3b
Brocade X6-4 IBM 8961-F0 (SAN256B-6)	9.0.1c

Brocade 620 IBM 8960-F64 8960-N64 SAN64B-6	9.0.1c,8.2.3b
Brocade X7-8 IBM 8961-F78 (SAN512B-7)	9.0.1c
Brocade X7-4 IBM 8961-F74 (SAN256B-7)	9.0.1c
Brocade G720 IBM 8960-R64/8960-P64 (SAN64B-7)	9.0.1c
Cisco MDS9250i IBM 8977-R50 (SAN50C-R)	9.2(1),8.5(1)
Cisco MDS9710 IBM 8978-E08 (SAN384C-6)	9.2(1),8.5(1)
Cisco MDS9706 IBM 8978-E04 (SAN192C-6)	9.2(1),8.5(1)

PROBLEM FIXES:

Problems fixed in this level are described below. There are 267 enhancements/defects fixed in this release; 74 defects occurred or were related to problems in client installations. They are described below with the following designations:

HIPER = High Impact & Pervasive

- **High Impact** = Loss of access or loss of data
- **Acute** = An unrecoverable error with potential loss of data
- Serious = An unrecoverable error with potential loss of access to data
- Moderate = A system path is not operational and performance might be degraded
- Service = A recoverable error, Service Improvements
- Improvement = Improvement for better usability

Pervasive: problems with 3 or more occurrences

High Impact: Grid Unjoin: Add stronger warnings about skipping consistency checks Pervasive: No Reference: 93035 Acute: Grid: Excessive polling for grid state information resulting in heartbeat loss between components and a reboot Pervasive: YES Reference: 92029

Acute: Security: Authentication issue when using local proxy Pervasive: YES Reference: 91991 Serious: Grid Flash Copy: Flash copy failed when lvols in mount pending Pervasive: No Reference: 92699

Serious: Grid Tape Attach: Memory leak in code that tracks volumes in cache. Pervasive: No Reference: 92355

Serious: Grid: Memory leak when opening files Pervasive: No Reference: 92214

Serious: Grid: Timing issues due to incorrect sequencing when calling secure socket layer (SSL) library routines Pervasive: No Reference: 91801

Serious: Grid: Timing issues due to incorrect sequencing when calling secure socket layer (SSL) library routines Pervasive: No Reference: 91741

Serious: Copy Export: Copy export can't be executed after physical library maintenance Pervasive: No Reference: 91292 Serious: RAS: Incorrectly fenced a cluster due to a lost cache path when it successfully switched to the secondary path Pervasive: No Reference: 91001

Serious: TS7700 Config: Add a warning about resizing a tape partition Pervasive: No Reference: 89239

Serious: Grid: Memory leak when network errors occur Pervasive: No Reference: 84951

Serious: Host IO: Unable to unmount a stand-alone device after host IPL Pervasive: No Reference: 92914

Serious: RAS: Upgrade local disk firmware fails Pervasive: No Reference: 92894

Serious: ACT_FINIS failed - Failed to configure network for GPFS - etc/ssh/sshd_config line 205: Subsystem 'sftp' already defined Pervasive: No Reference: 92882 Serious: Code Activation: Issue with increasing the size of a filesystem Pervasive: No Reference: 92836

Serious: RAS: Fixed issue with failed remove and replace of FCS adapter Pervasive: No Reference: 92817

Serious: RAS: Unable to configure Idap on ts7700 using name Pervasive: No Reference: 92813

Serious: Security: Server certificate is not replaced until web server is restarted Pervasive: No Reference: 92705

Serious: Performance: Slow filesystem response Pervasive: No Reference: 92648

Serious: Management Interface: Issue updating category expiration time Pervasive: No Reference: 92597

Serious: RAS: Need more context of what an MDE 8101 error indicates Pervasive: No Reference: 92534 Serious: Host IO: AIX panic when an uninitialized tape device was accessed Pervasive: No Reference: 92341

Serious: RAS: On CSA cache, the parser that checks for errors is creating logs so big that it is filling up the hydlog directory Pervasive: YES Reference: 92228

Serious: Grid: System ran out of memory and trapped. Pervasive: No Reference: 92227

Serious: Grid Tape Attach: Code bug when multiple physical volume reclamations are in process and a logical volume is recalled from one of those tapes. This results in a cluster rebooting Pervasive: YES Reference: 92164

Serious: Frame Swap: Code missing to backup to DVD RAM Pervasive: No Reference: 92122

Serious: RAS: System checkout not detecting when a filesystem is unmounted Pervasive: No Reference: 91744 Serious: Grid: Filesystem became unmounted and we failed to fence the cluster resulting in failed mounts Pervasive: No Reference: 91740

Serious: Cluster Renumber MES: Improve restart on a cluster renumber failure Pervasive: No Reference: 91641

Serious: Security: Enhance security with LDAP user information Pervasive: No Reference: 91586

Serious: Grid: Unable to remove a cluster from a family Pervasive: No Reference: 91237

Serious: Grid Tape Attach MES: Volumes written to a cluster after a Tape Attach MES was performed were written to the wrong pool Pervasive: No Reference: 91162

Serious: HYDME1189I and unable to logout _vts_ras id's and unable to use DNS name in RSYSLOG Pervasive: No Reference: 90997 Serious: RAS: After a cluster fenced and rebooted, the status checking was locked out Pervasive: No Reference: 90774

Serious: Grid: Reboot of a cluster in service resulted in online cluster going offline to the host Pervasive: No Reference: 87654 Moderate: Host Communications: Ficon panic when a write fails Pervasive: No Reference: 92669

Moderate: RAS: Timing issue resulted in multiple call home processes running simultaneously and resulted in a memory leak Pervasive: No Reference: 91973

Moderate: Database Maintenance: In a failure scenario, online reorg failed to cleanup a flag that blocked cache walk Pervasive: No Reference: 92350

Moderate: Grid: Timing issue when closing volumes causes a delay. Pervasive: No Reference: 92196

Moderate: Performance: Cache statistics queries from database slow requiring an index update Pervasive: No Reference: 92168

Moderate: Performance: Slow return to scratch processing requires a database index change to check LWORM values Pervasive: YES Reference: 92147 Moderate: Security: Issue receiving signer information for a certificate Pervasive: No Reference: 92888

Moderate: Management Interface: Improvements to the Web Code Updater installation Pervasive: No Reference: 92842

Moderate: Performance: DB2 backup checking improvements Pervasive: No Reference: 92523

Moderate: Cluster reboot after backward time adjustment Pervasive: No Reference: 92281

Moderate: Grid Tape Attach: Delayed premigration not honored during on-line transition. Pervasive: No Reference: 92279

Moderate: Grid BVIR: BVIR request for volume data on a 4 million volume database fails to create an output file Pervasive: No Reference: 92237

Moderate: RAS: fcs adapter replacement failed because of a firmware incompatibility Pervasive: No Reference: 92190 Moderate: Tape Attach: Add first time data capture for monitoring the physical device daemon - process died Pervasive: No Reference: 92117

Moderate: Grid: Local fencing of a cluster not working correctly when box is sick but not dead (SBND) Pervasive: YES Reference: 91943

Moderate: Grid Flash Copy: Write protect exclude categories not all identified with LIBREQ Pervasive: No Reference: 91936

Moderate: RAS: Call home for failed DDM need to include FRU Pervasive: No Reference: 91935

Moderate: RAS: vtd_exec status shows installed when it failed Pervasive: No Reference: 91887

Moderate: RAS: Enhance the cache path checking Pervasive: No Reference: 91749

Moderate: Security: Secure Data Transfer certificate validation fails after code load Pervasive: No Reference: 91704 Moderate: Security: MI not disabling HTTP in all cases Pervasive: No Reference: 91560

Moderate: Security: Permanently disable SHA1 ciphers Pervasive: No Reference: 91509

Moderate: Security: Can't login when box is offline. Pervasive: No Reference: 91060

Moderate: Security: Unable to login to MI when LDAP is enabled locally on one cluster and remote cluster is configured for local policy Pervasive: YES Reference: 91006

Moderate: Grid Join: Issues when setting data_deleted=Y on joining/merging cluster. Inherit value from existing cluster Pervasive: No Reference: 89957 Service: RAS: Disable ping to key servers Pervasive: No Reference: 91236

Service: RAS: Old interventions are left on the machine and resurface after a reboot reporting SERIOUS alert. Pervasive: YES Reference: 91135

Service: RAS: Improve handling of special characters when parsing log files for cache Pervasive: No Reference: 91721

Service: Tape Attach: Incorrect ERA and library status states paused when operational Pervasive: No Reference: 92367

Service: Security: Fixed issue resulting in SSL certificate validation failure when using client CA certificate Pervasive: No Reference: 91930 Improvement: Grid Join: Clarify filesystem error reasons when encountered Pervasive: No Reference: 92646

Improvement: RAS: After installing FC 5282 (disk encryption) FIPS compliance was registering as N Pervasive: No Reference: 91990

Improvement: RAS: Increase the size of /tmp filesystem for exec installation Pervasive: No Reference: 92818

Improvement: RAS: First time install (FTI) disable the lights on cache enclosures after a failure Pervasive: No Reference: 92120

Improvement: RAS: Automatically clear TS7700 MI Events for key server errors 0xEE31 and 0xEE32 when condition is corrected Pervasive: No Reference: 91745

Improvement: Grid Merge/Join: Merge/Join does not work with single-Use LDAP Authentication Pervasive: No Reference: 91402 Improvement: Grid Join: Issues when setting data_deleted='Y' on joining/merging cluster for volumes in 0xFF00. Inherit value from existing cluster Pervasive: No Reference: 89506

Improvement: RAS: Add some additional error reporting Pervasive: YES Reference: 83706