

IBM TS3500/3584 Libraries

=====

There were no changes in library manager configuration file for TS3500/3584 libraries.

IBM 3494 Libraries

=====

Changes in Library Manager configuration file for 3494 library:

ReportCategory must not be specified in config file => categories will be reported to iRMM:

<IBM3494>

<Handle>/dev/lmcp0</Handle>

<InjectCategory>0xFF00</InjectCategory>

<ReportCategory>0x012C</ReportCategory>

<Slottype>3480</Slottype>

<DriveSerial report="false"/>

<MountTime>30</MountTime>

<AutoQuery enable="false">

<Sleep>10</Sleep>

</AutoQuery>

...

</IBM3494>

New parameter in Library Manager configuration file for 3494 library:

<IBM3494>

...

<Demount wait="true"/>

</IBM3494>

Sun/StorageTek Libraries

=====

There were no changes in library manager configuration file for STK libraries.